

SOUTH AFRICAN CIVIL AVIATION AUTHORITY

Ref: 7455

ACCIDENT REPORT – EXECUTIVE SUMMARY

Aircraft Registration	ZS-FZS		Date of Accident	24 January 2002		Т	Time of Accident		1600Z
Type of Aircraft	PARTENAVIA P		64B Type of		of Operation		Training		
Pilot-in-command Licence Type			Commercial	Age	56	Li	cence Valid	alid Yes	
Pilot-in-command Flying Experience			Total Flying Hours	16564	16564.0		ours on Type	650.0	
Last point of departure Rus		Rustenburg Aerodrome (FARG).							
Next point of intended landing Rus		Rustenburg Aerodrome (FARG).							
Location of the accident site with reference to easily defined geographical points (GPS readings if possible)									
On runway 34, Rustenburg Aerodrome.									
Meteorological Inform	eteorological Information CAVOK, Wind: Calm, Temperature: 26°C								
Number of people on	board 2 +	F 0	No. of people injured		Nil	No. of people ki		lled	Nil
Synopsis			•						•

While pushing the aircraft out of the hangar, the pilot noted that the nose wheel torque link was extended in an unusual and opposite direction. The pilot then pushed the torque link back to its normal position with his foot and everything appeared to be normal.

During a touch-and-go landing, with the student pilot flying, the nose wheel rotated through $\pm 90^{\circ}$ with the nose wheel oleo strut, which consequently failed and resulted in the propeller making contact with the runway surface.

On inspection, it was noted that the nose wheel torque link centre bolt had failed.

The last Mandatory Periodic Inspection prior to the accident was certified on 18 November 2001 at 2393.0 airframe hours and the aircraft accumulated a further 61.0 flying hours since the last MPI.

Probable Cause

The nose wheel torque link centre-bolt failed during a touch and go landing, causing the oleo strut to rotate through $\pm 90^{\circ}$ and resulting in a substantial load on the strut during touch down which caused it to fail.