

SOUTH AFRICAN CIVIL AVIATION AUTHORITY

Ref: 7591

ACCIDENT REPORT – EXECUTIVE SUMMARY

		-						
Aircraft Registration	ZS-RIK	Date of Accident	20 Nov 2	2002 Time of Accident		0830Z		
Type of Aircraft	ROBIN	Type of Operation			Game / Live stock cull			
Pilot-in-command Licence Type		Commercial	Age	37 Li		cence Valid	Yes	
Pilot-in-command Flying Experience		e Total Flying Hours	1001.12		Н	ours on Type	597.2	
Last point of departur	e E	Buffelsdrift farm in the Northern Province, near Ellisras						
Next point of intended	ded landing Buffelsdrift farm in the Northern Province, near Ellisras							

Location of the accident site with reference to easily defined geographical points (GPS readings if possible)

Buffelsdrift farm in the Northern Province, near Ellisras

Meteorological Information	Fine weather conditions prevailed at the time of the accident. The wind was easterly at 5 knots. There was no cloud and the prevailing temperature was recorded as 25°C.								
Number of people on board	1+1	No. of people injured	0	No. of people killed	0				
Synopsis									

On 20 November 2002 at approximately 0830Z, during fine weather conditions, the pilot, accompanied by a passenger, was engaged in a game darting exercise.

After some time in the air the helicopter ran short of fuel. The pilot landed the helicopter and additional fuel was added from drums by the owner of the helicopter.

A short while later the pilot took-off again, but approximately 100m away from the take-off point the engine started running rough and the low rotor RPM warning sounded. The pilot attempted to land the helicopter downwind, but a hard landing followed. The latter resulted in the skids collapsing and the main rotor made contact with some dense bush.

The AMO recovering the helicopter, reported that the fuel in the drums were contaminated by water.

The pilot was correctly licenced and type rated on the aircraft type and held a valid medical certificate as a commercial pilot, valid until 28 February 2003. He was also the holder of a Cull rating for game and live stock.

According to available records the aircraft was correctly maintained. The last MPI was certified on 16 September 2002 at 5323.9 airframe hours and the aircraft has accumulated a further 61.1 airframe hours since the last MPI.

No on-site investigation was carried out.

Probable Cause

The aircraft was refuelled with contaminated fuel.