



## SOUTH AFRICAN CIVIL AVIATION AUTHORITY

## **ACCIDENT REPORT - EXECUTIVE SUMMARY**

Aircraft Registration	ZU-BDJ Date of Accide		Date of Accident	8 September 2003		Time of Accident	0920Z
Type of Aircraft	SUKHOI SU-29			Type of Operation		Private	
Pilot-in-command License Type			Private	Age	46	License Valid	No
Pilot-in-command Flying Experience			Total Flying Hours	840		Hours on Type	317
Last point of departure Nelspru			spruit Aerodrome	•			
Next point of intended	l landing	ding Ermelo Aerodrome					

Location of the accident site with reference to easily defined geographical points (GPS readings if possible)

17.6 nm South West of Nelspruit (Kaapsehoop area)

Meteorological Information	It was overcast with dense fog. <b>Wind</b> : NNE at 5 knots <b>Temperature</b> : 16°C							
Number of people on board	1+1	No. of people injured	0	No. of people killed	1+1			
Synopsis								

The pilot accompanied by a passenger departed Nelspruit Airport at 0848Z to Ermelo. According to the ATC at Nelspruit the pilot was instructed to remain VFR not higher than 5000 ft due to traffic on NSV Approach for FAKN. The pilot reported that he was above cloud and would stay at 4500 ft.

The ATC also stated that the weather within FANS special Rules area was VMC with good visibility and overcast with a cloud base of approximately 1500 ft or more. The cloud to the west was much lower and the Kaapsehoop mountain was not visible, but the Schoemans valley was open.

At 0920Z a witness standing approximately 1.3 nm south of the accident site heard an aircraft flying and shortly thereafter heard a thud but could not observe anything due to the thick fog. His wife tried to phone the ATC but was unable to reach them.

The witness and a friend started a search and at approximately 1230Z they heard a helicopter flying. Confirmation was received that an aircraft had crashed and the wreck was later located in the vicinity where the helicopter was flying.

On arrival at the scene of the accident the witness observed that both occupants were fatally injured and that the ensuing fire destroyed the aircraft. The SAPS were advised accordingly.

The pilot was not licensed.

The last annual inspection was certified on 20 December 2002 at 316 flying hours. The aircraft had accumulated a further 13 flying hours since the last inspection was certified.

## **Probable Cause**

Pilot was cleared VFR to remain VMC below 5000ft, and inadvertently entered IMC conditions and subsequently collided with high ground fatally injuring the pilot and passenger.