Ref: 7791



SOUTH AFRICAN CIVIL AVIATION AUTHORITY

ACCIDENT REPORT – EXECUTIVE SUMMARY

Aircraft Registration	ZS-WHM		Date of Accident	1 May 2004		Time of Accident		0815Z		
Type of Aircraft	WINDL		ASS TRIKE	Type of Operation		on	Private			
Pilot-in-command Licence Type			Private	Age	42	L	icence Valid	Yes		
Pilot-in-command Flying Experience			Total Flying Hours	355.8		Н	ours on Type	irs on Type 11.7		
Last point of departure Del			Delta 200 Aerodrome							
Next point of intended landing De		Delta 200 Aerodrome (RWY 20)								
Location of the accident site with reference to easily defined geographical points (GPS readings if possible)										
On Runway 20 at Delta 200 Aerodrome										
Meteorological Inform	ation SV	SW wind at 4kts. Visibility: >10km and Temperature: +18°C								
Number of people on	ooard 1+0		No. of people in	jured	d 0		lo. of people killed		0	
Synopsis			•							

The pilot was engaged in a local flight and landed in light cross wind conditions on Runway 20 at Delta 200. The pilot experienced difficulty in maintaining directional control on landing as the aircraft had a tendency to fly left wing low at about 15°. The wing was subjected to recent repairs and rigging by the manufacture (Solo Wings). It was also flown by two other instructors who confirmed this tendency. During the landing roll the aircraft departed the runway to the right and encountered soft sand which caused the main wheel and the nose wheel to fail. This resulted in the aircraft to dig in and overturn. The pilot was not injured.

The aircraft was issued with a Private Authority to Fly on 30 October 2003. The last Annual Inspection was certified on 15 October 2003 at 467.15 flying hours and the aircraft was operated for 8.02 hours since the last Annual Inspection.

No on-site investigation was conducted.

Probable Cause

When the wing was received back from the manufacturer, after repairs were carried out on it, the aircraft had a tendency to turn to the left. During a cross-wind landing the pilot attempted to correct the left turn by applying right turn controls but was unable to control the wing in order to settle the aircraft on the runway. The aircraft landed on soft sand on the right hand side off the runway.