## **EXECUTIVE SUMMARY - AIRCRAFT ACCIDENT REPORT**

					Reference	ce:	CA18/2/3/8069			
Aircraft Registration	ZU-CFK		Date of Accident	23 Jan	23 January 2006		Time of Accident 10		030Z	
Type of Aircraft	Windlass Aquilla		a (Z-159)	Type of Operation		ion	Private			
Pilot-in-command Licence Type		Microlight	Age	<b>.ge</b> 47		Licence Valid Yes				
Pilot-in-command Flying Experience		erience	Total Flying Hours	1 040	1 040		Hours on Type	/pe 997.05		
Last point of departure Wi		ntervogel Aerodrome, near Malmesbury (FAWF)								
Next point of intended landing W		g Win	/intervogel Aerodrome (FAWF)							
Location of the accide	ent site v	with refe	erence to easily defir	ned geog	graphical	poir	Its (GPS readings if	oossib	ole)	
800 m on approach to t	he grave	l runway	,							
Meteorological Information		Surface wind 160°, gusting at $10 - 20$ kts, visibility 10 km, temperature $17$ °C								
Number of people on board		1 + 1	No. of people injured		1 + 1	No.	lo. of people killed		0	
Synopsis	Svnopsis									
			owards the runway for	an emerg	gency land	ling b				
runway, crashing in a n The engine was ground the reported engine fail The pilot was appropria existing regulations. The last annual inspecti	earby fie tested by ure could tely licer on was o	Id and n y an app d not be nsed, me certified o	owards the runway for a osing over. The aircra roved person and four determined. edically fit with no rest on 20 November 2005	an emerg ift was su nd to be s rictions a 5 at a tota	gency lanc ubstantiall atisfactor and qualifi al of 998.2	ling b y dar y at a ed fo 4 airl	ut the aircraft did n naged. Il power settings. T r the flight in acco rame hours. At the	ot rea he ca rdanc e time	ach the ause o ce with	
runway, crashing in a n The engine was ground the reported engine fail The pilot was appropria	earby fie tested by ure could tely licer on was o	Id and n y an app d not be nsed, me certified o	owards the runway for a osing over. The aircra roved person and four determined. edically fit with no rest on 20 November 2005	an emerg ift was su nd to be s rictions a 5 at a tota	gency lanc ubstantiall atisfactor and qualifi al of 998.2	ling b y dar y at a ed fo 4 airl	ut the aircraft did n naged. Il power settings. T r the flight in acco rame hours. At the	ot rea he ca rdanc e time	ach the ause o ce with	
runway, crashing in a n The engine was ground the reported engine fail The pilot was appropria existing regulations. The last annual inspecti accident, the aircraft ha	earby fie tested by ure could tely licer on was o d flown a	ld and n y an app d not be nsed, me certified o a further	owards the runway for a osing over. The aircra roved person and four determined. edically fit with no rest on 20 November 2005 26.1 airframe hours s	an emerg ft was su nd to be s rictions a o at a tota ince the	gency land ubstantiall and qualifi al of 998.2 last annu	ling b y dar y at a ed fo 4 airl	ut the aircraft did n naged. Il power settings. T r the flight in acco rame hours. At the	ot rea he ca rdanc e time	ach the ause o ce with	

CA 12-13a 23 FEBRUARY 2006 Page 1 of 1
--