SOUTH AFRICAN

CIVIL AVIATION **AUTHORITY**

EXECUTIVE SUMMARY - AIRCRAFT ACCIDENT REPORT

Form Number: CA 12-13a

					Reference	е	CA18/2/3/8240			
Aircraft Registration	ZS-MHP		Date of Accident	12 Jar	2 January 2007		Time of Accident		0738Z	
Type of Aircraft	Piper PA46 – 31		10 P	Type of		on	Private			
Pilot-in-command Licence Type			Private Pilot	Age	67		Licence Valid Yes		3	
Pilot-in-command Flying Experience			Total Flying Hours	2 637.	37.04		Hours on Type	1 303.53		
Last point of departure Ge		Geo	George Aerodrome (FAGG)							
Next point of intended landing Still		Stilbay Aerodrome								
Location of the accident site with reference to easily defined geographical points (GPS readings if possible)										
On landing on runway 27 at Stilbay Aerodrome										
Meteorological Inform	allon	CAVOK, wind 045° at 12 – 15 kts, temperature 25°C, clouds broken at 1 800 ft								
Number of people on board 1 + 0		No. of people injured		0 No.		. of people killed		0		
Synopsis										

The pilot was on a return flight from George Aerodrome (FAGG) to Stilbay.

The approach to Stilbay Aerodrome was fine, but on touchdown the aircraft was subjected to a wind shear. As a result of the wind shear, the pilot lost directional control resulting in a runway excursion 20 m to the left from the touchdown point. According to the pilot, the wind shear occurred as a result of the wind that was blowing from the left just below the tree span along the left of the approach path.

A possibility exists that following the wind shear, the aircraft had a hard landing. This resulted in the pilot losing directional control of the aircraft and a subsequent runway excursion.

The pilot sustained no injuries as a result of this accident. The aircraft sustained damage to the left main gear, nose gear and propeller.

The last mandatory periodic inspection (MPI) was carried out on 10 July 2007 at 1 699.0 flying hours, and the aircraft was further operated for 28.0 flying hours since.

Probable Cause

Loss of directional control due to a hard landing following a wind shear condition during landing.

IARC Date	21 April 2008	Release Date	Reviewed by EM office: AIID November 2009
-----------	---------------	--------------	--