

SOUTH AFRICAN CIVIL AVIATION AUTHORITY

Ref: 7160

ACCIDENT REPORT – EXECUTIVE SUMMARY

| Date of Accident | 28 February 2000 | Time of Accident | | 0600Z | | |
|------------------------------------|------------------|-----------------------|------|------------------------|-----|--|
| Aircraft Registration | ZS-ICE | Type of Aircraft | | PA 25-235 | | |
| Pilot-in-command Licence Type | | Commercial | | Licence Valid | Yes | |
| Pilot-in-command Flying Experience | | Total Flying Hours | 3789 | Total Hours on Type | 630 | |
| Type of Operation | | Agricultural | | | | |
| Last point of departure | | Lichtenburg | | | | |
| Next point of intended landing | | Lichtenburg | | | | |
| 1 | | | | | | |

Location of the accident site with reference to easily defined geographical points (Plus GPS readings if possible)

Farm in Lichtenburg district

| Meteorological Information | Fine weather conditions prevailed at the time of the accident | | | | | |
|----------------------------|---|-----------------------|---|----------------------|---|--|
| Number of people on board | 1+0 | No. of people injured | 0 | No. of people killed | 0 | |
| Synopsis | | | | | | |

The pilot admitted that he ran out of fuel during a crop spraying detail, followed by a forced landing in a sunflower field.

The aircraft sustained substantial damage during the accident.

The pilot held a valid licence and the aircraft type was endorsed to his licence. He was restricted to wear corrective lenses.

Fine weather conditions prevailed at the time of the accident.

The owner was not in possession of an operator licence.

According to available documentation the aircraft was correctly maintained.

NB: This was an off-site investigation

Probable Cause

The pilot admitted that the aircraft ran out of fuel.