



J10/2/7272

A00-129

SOUTH AFRICAN CIVIL AVIATION AUTHORITY

ACCIDENT REPORT – EXECUTIVE SUMMARY

Date of Accident	27/09/00	Time of Accident	1830Z		
Aircraft Registration	ZS-OKM	Type of Aircraft	Beech 1900D		
Name of Owner		Name and Number of Operator			
National Airways Corporation (PTY) LTD		N/A (Ferry Flight)			
Pilot-in-command Licence Type	ATP	Age	56	Licence Valid	Yes
Pilot-in-command Flying Experience	Total Flying Hours		11628	Hours on Type	418
Last point of departure	FADN				
Next point of intended landing	FAVG				
Location of the accident site with reference to easily defined geographical points (plus GPS readings if possible)					
Taxiway B at Durban International Airport					
Meteorological Information	The weather was fine				
Number of people on board	1+1	No. of people injured	None	No. of people killed	None
Synopsis	<p>The aircraft was parked on the apron at parking bay No 10 and was cleared to taxi runway 06 for a ferry flight to Virginia. While taxiing to runway 06 on entering taxiway B an ACSA service bus collided with the right-hand wing of the aircraft. There were no injuries to persons but the aircraft was substantially damaged.</p> <p>The pilot stated that no beacon lights or lights were displayed and that the driver of the bus was taken away for an alcohol blood test.</p> <p>Temporary repairs were carried out on the aircraft and the aircraft was flown to NAC Virginia for further repairs.</p>				
Probable Cause					
Collision with ACSA service bus.					