SOUTH AFRICAN							CA1	8/2/3	/7259	
	SC	OUTH AFRICAN CIVIL AVIATION AUTHORITY								
CIVIL AVIATION AUTHORITY A	ACCIDENT REPORT – EXECUTIVE SUMMARY								,	
Date of Accident	27/10/2000			Time of Accident		1430Z				
Aircraft Registration	ZS-EBT			Type of Aircraft		PA28-235				
Name of Owner				Name and Number of Operator						
Fey CJ				Private						
Pilot-in-command Licence Type				Private	Age	52	Licence Valid	Y	Yes	
Pilot-in-command Flying Experience				Total Flying Hou	I Flying Hours		Hours on Type	489		
Last point of departure			Kokstad							
Next point of intended landin										
Location of the accident site with reference to easily defined geographical points (GPS readings if possible)										
Lusikisiki aerodrome										
Meteorological Information				poor visibility						
Number of people or board	<b>י</b> 1+2		2 No. of people injur		ured		o. of people 0			
Synopsis										
The pilot obtained a weather report, from the person who had to collect them from the aerodrome, before his departure from Kokstad.										
According to the pilot the weather information he received was very misleading and when he arrived at Lusikisiki he decided to do a precautionary landing as the weather had deteriorated to a point where a safe flight could not be conducted.										
The pilot then opted to land at the Lusikisiki aerodrome. During the two inspection flights of the runway he observed a number of ruts in the runway and decided to land on the grass next to the runway.										
During the landing the left wheel struck a grass covered anthill and caused the gear to separate from the aircraft.										
Probable Cause										
During the precautionary landing the aircraft struck a grass covered anthill.										