					Ref: 7348			
	SOUTH AFRICAN CIVIL AVIATION AUTHORITY							
		ACCIDENT REPORT – EXECUTIVE SUMMARY						
Date of Accident	4/5/2001	Time of Accident		0700Z				
Aircraft Registration	ZS-KOD	Type of Aircraft		Cessna C188				
Pilot-in-command Licence Type		Commercial		Licence Valid	Yes			
Pilot-in-command Flying Experience		Total Flying Hours	1600	Total Hours on Type	Unknown			
Type of Operation		Agricultural						
Last point of departure		Heatonville district – Private farm						
Next point of intended landing		Heatonville district – Private farm						

Location of the accident site with reference to easily defined geographical points (plus GPS readings if possible)

S28º 39,11' E031º 46,58'

Meteorological Information	Fine					
Number of people on board	1+0	No. of people injured	1	No. of people killed	0	
Synopsis						

On 4 May 2001 the pilot was busy with a crop spraying detail in the Heatonville district when he experienced engine problems and crashed.

The aircraft was destroyed by the impact forces and two power lines were severed during the attempted forced landing

The pilot sustained serious injuries during the accident.

The pilot held a valid licence, with the aircraft type endorsed onto his licence. He was also the holder of a Night flight- and an Agricultural rating.

The aircraft was not airworthy at the time of the accident.

According to the pilot and witnesses, fine weather conditions prevailed at the time of the accident.

The pilot's safety harness failed during the accident and he was flung out of the aircraft, ending-up underneath the aircraft. Bystanders had to lift the aircraft in order to free the pilot.

The final MPI was over flown by 295.09 Hrs.

It would appear that the propeller was serviceable prior to the accident.

The registered owner was not in possession of an Operators Licence in accordance with the Domestic Air Services Licence Act.

Probable Cause

Possible fuel contamination as a result of a lack of regular maintenance.