

SOUTH AFRICAN CIVIL AVIATION AUTHORITY

Ref: 7539

ACCIDENT REPORT – EXECUTIVE SUMMARY

			_		0=100					= 1 0 7	
Aircraft Registration	ZS-ORT		Da	ate of Accident	05/08/2002		Tim	ime of Accident		1518Z	
Type of Aircraft	PIPER PA28-23				Type of Operat		tion	ion Private			
Pilot-in-command Licence Type			Pr	ivate	Age	e 41		icence Valid	e Valid Yes		
Pilot-in-command Flying Experience			Тс	otal Flying Hours	204,7 hrs		ŀ	Hours on Type	75.9 hrs		
Last point of departure			Hoedspruit								
Next point of intended landing		Swartkops Aerodrome									
Location of the accide	ent site v	vith ref	eren	ce to easily define	ed geog	graphica	al poi	nts (GPS reading	s if po	ssible)	
Next to Runway 02 at S	wartkops	s Aerod	rome	9.							
Meteorological Inform	Fine										
Number of people on board 1		1 + 1	1 + 1 No. of people inj		jured	Nil No		o. of people kil	o. of people killed		
Synopsis							•				
The aircraft was on a at Swartkops Aerod The pilot stated tha landing was "straigh left, although the pilo The nose landing ge The tyre marks obse nose wheel and left	Irome a t the fir and s ot attem ear colla erved or	ind position oft". D opted to apsed a n the ru	sition proa Durin o co and unw	ned the aircraft ch to the runwa og the touch dow rrect the situation the propeller ar ay surface sugg	to land ay was wn the on the a nd right	d on Ru flown a aircraft aircraft o -hand v	unwa as u vee depa wing	ay 02. sual. He stat red off the run arted the runw tip contacted	ted t nway vay s the g	hat the y to the urface pround	

Probable Cause

Due to the pilot's landing technique he lost directional control of the aircraft during the landing.