Ref: 7569



SOUTH AFRICAN CIVIL AVIATION AUTHORITY ACCIDENT REPORT – EXECUTIVE SUMMARY

Aircraft Registration	ZS-HLC		Date of Accident	25/10/2002		Time	Γime of Accident		1530Z	
Type of Aircraft	ROBINS	SON R	22	Type of Operation		tion	Game Capture			
Pilot-in-command License Type			Commercial - Helicopter	Age	24	L	icense Valid	Yes		
Pilot-in-command Flying Experience			Total Flying Hours	871	Hours on Type			752		
Last point of departure Nyls			Nylsvlei Nature Reserve							
Next point of intended landing Nyls			Nylsvlei Nature Reserve							
Location of the accident site with reference to easily defined geographical points (GPS readings if possible)										
Nylsvlei Nature Reserve										
Meteorological Inform	nation	The weather was fine with a 10 knot north westerly wind								
Number of people on	board	1 No. of people in		njured	jured None		No. of people kille		None	
Synopsis			<u> </u>			•				
Danis a a second		!	Ale a sellet ellerreed	41			/ ta dasa			

During a game capture operation the pilot allowed the main rotor RPM to decay while turning down-wind and collided with the ground.

The pilot was not injured but the helicopter was substantially damaged.

The aircraft was maintained as prescribed and the next MPI was due on 25 July 2003 or at 4362 hours whichever occurred first. The aircraft was operated for 88 hours since the last MPI.

The operator was in procession of a valid operator's license No G 543 D

Probable Cause

The pilot failed to maintain Main Rotor RPM.