



## **SOUTH AFRICAN CIVIL AVIATION AUTHORITY**

## ACCIDENT REPORT – EXECUTIVE SUMMARY

Aircraft Registration	ZS-NHK	ζ	Date of Accident	03-12-2002 Time of Accident		0835 Z		
Type of Aircraft	PIPER PA22-150			Type of Operation		tion	Conversion Flight	
Pilot-in-command License Type			Commercial	Age	62 year	s Li	icense Valid	Yes
Pilot-in-command Flying Experience			Total Flying Hours	18133		Н	ours on Type	45
Last point of departur	f departure Lanseria Aerodrome							
Next point of intended landing Lans			nseria Aerodrome					

Location of the accident site with reference to easily defined geographical points (GPS readings if possible)

## Lanseria Aerodrome

Meteorological Information	The weathedirections	er was fine, the temperatu	with the wind variable from all		
Number of people on board	2+0	No. of people injured	Nil	No. of people killed	Nil
Synopsis					

The Instructor stated that on a conversion training flight at Lanseria Aerodrome, he demonstrated a short field take-off to the student pilot when he felt a pronounced shimmy on the tail wheel of the aircraft.

However, after they had completed three successful touch-and-go landings on Runway 06R, he closed the throttle during the flare prior to a full stop landing, but upon landing the tail wheel started to shimmy and the aircraft started to veer to the right. He then attempted corrective action with the rudder and tail wheel steering system and brakes, but to no avail. The aircraft veered off the runway to the right, onto the grass and the left-hand main landing gear collapsed.

The pilot was in possession of a valid Commercial pilot's license and Instructor Grade II rating.

The Flight Training School was in possession of a valid Operator's License No. CAA/0065 and the flight was duly authorized.

The aircraft landed on Runway 06R in light but variable wind conditions.

## **Probable Cause**

The Instructor lost directional control after landing in variable wind conditions and the fact that the tail wheel assembly failed to turn to the left hand side, contributed to the cause of the accident