Ref: 7659



SOUTH AFRICAN CIVIL AVIATION AUTHORITY

ACCIDENT REPORT – EXECUTIVE SUMMARY

Aircraft Registration	ZS-HRL		Date of Accident	20 Ma	y 2003	Time of Accident		±0900Z	
Type of Aircraft	ENSTROM 280C			Type of Operation			Private		
Pilot-in-command License Type			Private	Age	49 L		icense Valid	No	
Pilot-in-command Flying Experience			Total Flying Hours	705.9		Н	lours on Type	447.6	
Last point of departure With			/itbank aerodrome						
Next point of intended landing With		oank aerodrome							

Location of the accident site with reference to easily defined geographical points (GPS readings if possible)

On the farm Hartebeeslaagte, 10 nm South West of Witbank aerodrome.

Meteorological Information	CAVOK								
Number of people on board	1+1	No. of people injured	Nil	No. of people killed	Nil				
Synopsis									

According to the pilot he occupied the left seat and was accompanied by a passenger (who was a vehicle tracker and was seated in the right seat with airborne tracking equipment onboard) and was on a private flight in the Witbank area when the CHT (Cylinder Head Temperature) indication suddenly decreased. He then decided to execute a precautionary landing on an open field approximately 10nm South-West from Witbank aerodrome.

During the approach to land, the helicopter main rotor blades collided with a telephone pole situated to the right of the helicopter.

The helicopter collided with the ground approximately 12m further on and was substantially damaged in the process.

None of the occupants were injured in the accident.

Probable Cause

Following an erroneous CHT indication, the pilot attempted to carry out a precautionary landing on an open field but failed to notice telephone lines and a wooden telephone pole to the right of the aircraft. A main rotor strike followed which rendered the helicopter uncontrollable and resulted in a subsequent collision with the ground 12m further on.