

SOUTH AFRICAN CIVIL AVIATION AUTHORITY

Ref: 7833

## **ACCIDENT REPORT – EXECUTIVE SUMMARY**

12									
Aircraft Registration	ZS-DKN		Date of Accident	15 July 2004			Time of Accident	1500Z	
Type of Aircraft	CESSNA 180			Type of Operation		tion	Private		
Pilot-in-command Licence Type			Private	Age	61	L	icence Valid	Yes	
Pilot-in-command Flying Experience			Total Flying Hours	2500		н	ours on Type	50	
Last point of departure Gra			Grand Central Aerodrome (FAGC)						
Next point of intended landing Haz		Hazy	lazyview Aerodrome						
Location of the accide	ent site with	n refer	ence to easily defir	ned geog	graphica	l poi	nts (GPS reading	gs if pos	sible
Hazyview Aerodrome									
Meteorological Inform	ation CA	CAVOK, Wind: 135°/10kt, Temperature: 16°C							
Number of people on board 1+2		2	No. of people in	jured 0		No	o. of people ki	lled	0
Synopsis									

The pilot had just landed on Runway 17 and had slowed down in order to carry out a 180° turn to backtrack on the runway.

The aircraft was taxied close to the left hand edge of the runway and as the pilot initiated the right turn, the tail wheel passed through a ditch covered by grass. This caused damage to the rear fuselage and tail wheel.

The pilot and passengers sustained no injuries.

The aircraft had a valid Certificate of Airworthiness which had been issued on 02 December 2003. The last MPI was certified on 14 November 2003 at 8623.00 flying hours. The aircraft had accumulated a further 63.96 flying hours.

## **Probable Cause**

The pilot misjudged his proximity to the left hand edge of the runway and during the right hand turn in order to backtrack the runway, the tail wheel passed through a ditch which caused damage to the rear fuselage and tail wheel.