

## **EXECUTIVE SUMMARY - AIRCRAFT ACCIDENT REPORT**

					Reference	:	CA18/2/3/797	1	
Aircraft Registration	ZS-JOC		Date of Accide	nt 07 Ju	ne 2005		Time of Acci	dent	0940Z
Type of Aircraft	Piper P	<b>\-34</b>		Туре	of Operation	n	Training		
Pilot-in-command Lice	ence Typ	е	Commercial	Age	46	L	icence Valid	Yes	i
Pilot-in-command Flyi	ng Expe	rience	Total Flying Hou	urs 12 33	3.0	Н	ours on Type	480	.0
Last point of departure	е	Wo	nderboom Aerodr	rome (FAW	B)				
Next point of intended	landing	Wo	nderboom Aerodr	rome (FAW	B)				
Location of the Accide	ent site v	vith refe	erence to easily of	defined ge	ographical	poi	1ts (GPS reading	js if po	ssible)
On runway 29 next to th	ie interse	ction of	runway 24 at Wo	nderboom /	Aerodrome				
Meteorological Inform	ation	CAVOK	, surface wind ca	lm, tempera	ature 23°C, (	QNI	H 1023		
Number of people on	board	2 + 1	No. of peop	le injured	0	No	o. of people ki	lled	0
Synopsis					1				I
general flying area (GF) The instructor stated that	A). at on thei	return		anned to ca	rry out a few	cire	cuits and landir	igs. Di	uring the
general flying area (GF/ The instructor stated tha first landing, they touched nose gear touched down was down and locked. H the runway so as not to The owner questionnaire it does not indicate wha The last mandatory per aircraft was operated fo The last audit on the avi Approval was issued on	A). at on thei ed down r n. He cor de further block the e indicate t failed e iodical in r a further ation trai	return f ormally firmed t stated f runway s that th cactly. spection r 66.84	to FAWB, they pla with both main lan hat there were thr hat when the airc r for a long time. e cause of the nos (MPI) was carrie flying hours. anisation (ATO no	anned to ca nding gears ree green lig raft slowed se gear coll ed out on 17 o. CAA/026	rry out a few . However, t ght indication down he tur apse was du 7 January 20 3) was carrie	circ he i ns ti nec e tc	cuits and landin hose gear colla hat indicated th the aircraft to mechanical fai at 3 634.14 fly	ngs. Dr psed v e lanc the lef lure. H	uring the when the ling gear t to clear lowever, urs. The
general flying area (GF/ The instructor stated tha first landing, they touched nose gear touched down was down and locked. H the runway so as not to The owner questionnaire it does not indicate wha The last mandatory per aircraft was operated fo The last audit on the avi	A). at on thei ed down r n. He cor de further block the e indicate t failed e iodical in r a further ation trai	return f ormally firmed t stated f runway s that th cactly. spection r 66.84	to FAWB, they pla with both main lan hat there were thr hat when the airc r for a long time. e cause of the nos (MPI) was carrie flying hours. anisation (ATO no	anned to ca nding gears ree green lig raft slowed se gear coll ed out on 17 o. CAA/026	rry out a few . However, t ght indication down he tur apse was du 7 January 20 3) was carrie	circ he i ns ti nec e tc	cuits and landin hose gear colla hat indicated th the aircraft to mechanical fai at 3 634.14 fly	ngs. Dr psed v e lanc the lef lure. H	uring the when the ling gear t to clear lowever, urs. The
general flying area (GF/ The instructor stated tha first landing, they touched nose gear touched down was down and locked. H the runway so as not to The owner questionnaire it does not indicate wha The last mandatory per aircraft was operated fo The last audit on the avi Approval was issued on	A). at on thei ed down i n. He cor le furthei block the e indicate t failed e iodical in r a furthe ation trai i 13 June	return f ormally firmed t stated f runway s that th cactly. spection r 66.84 hing org 2004 w	to FAWB, they pla with both main lat hat there were the hat when the airc of r a long time. e cause of the nos (MPI) was carrie flying hours. anisation (ATO no ith an expiry date	anned to ca nding gears ree green lig raft slowed se gear coll ed out on 17 o. CAA/026 e of 12 June	rry out a few However, t ght indication down he tur apse was du 7 January 20 3) was carrie 2005.	circ he i ns ti nec e tc	cuits and landin hose gear colla hat indicated th the aircraft to mechanical fai at 3 634.14 fly	ngs. Dr psed v e lanc the lef lure. H	uring the when the ling gear t to clear lowever, urs. The

CA 12-13b 23 FEBRUARY 2006 Page 1 of 1
--