



A00-040-7182

SOUTH AFRICAN CIVIL AVIATION AUTHORITY

ACCIDENT REPORT – EXECUTIVE SUMMARY

Date of Accident	13 April 2000	Time of Accident	0830Z		
Aircraft Registration	ZS-WFJ	Type of Aircraft	Pietenpol		
Name of Owner	Name and Number of Operator				
R. Reeve	Krugersdorp Flight School (CAA-0054)				
Pilot-in-command Licence Type	Student	Age	34	Licence Valid	Yes
Pilot-in-command Flying Experience	Total Flying Hours	28.5	Hours on Type	28.5	
Last point of departure	Krugersdorp				
Next point of intended landing	Krugersdorp				
Location of the accident site with reference to easily defined geographical points (plus GPS readings if possible)					
Krugersdorp Aerodrome					
Meteorological Information	Weather was fine				
Number of people on board	1	No. of people injured	0	No. of people killed	0
Synopsis	<p>The student pilot was engaged in circuit training when she lost directional control of the aircraft during landing. The aircraft veered off the runway into the long grass and the left undercarriage struck a molehill and the aircraft nosed over.</p> <p>Damage was caused to the left undercarriage, one propeller blade, air filter and minor damage to the engine cowling.</p>				
Probable Cause:					
Student lost directional control during the landing.					