Section/division Occurrence Investigation

AIRCRAFT ACCIDENT REPORT AND EXECUTIVE SUMMARY

Form Number: CA 12-12b

							Reference:		CA18/2/3/8038		
Aircraft Registration	ZS-PAT		Da	Date of Accident		18 Sep 2005	tember		Time of Accident		0800Z
Type of Aircraft Kitfox II			•			Type of Operatio		n	Private		
Pilot-in-command Licence Type		е	Ai	Airline Transport		Age 43		L	Licence Valid Yes		
Pilot-in-command Flying Experien		rience	Total Flying Hours		ours	151.9		Hours on Type		7.3	
Last point of departure		Kit	Kitty Hawk Aerodrome, Gauteng								
Next point of intended landing			Kitty Hawk Aerodrome, Gauteng								
Location of the accide	ent site w	ith ref	eren	ce to easily	defin	ed geog	graphical p	ioo	nts (GPS readings	if pos	sible)
Runway 01 at Kitty Haw	vk Aerodr	ome.									
Meteorological Inform	ation	Surface	e wir	nd: calm; ter	mpera	ture: 22	°C; visibili	ty g	jood		
Number of people on	board	1 + 1		No. of peop	ole inj	ured	0	No	o. of people kill	ed	0
Synopsis											
The pilot and the aircraft that during the taxi test contacted the runway supropeller, tail fin and fus Neither the pilot nor past The aircraft was issued of 1997, as amended of airframe hours and the	, the nos urface and selage. The ssenger w with a vali n 09 May	e wheed the air here we was injuited Author 2005.	el sta rcrafi ere a red. ority The	tred to shimit nosed over on the last annual in the	my, ar onto it nts on ate in nspec	nd then s roof. T the win terms of terms of	broke off. he aircraft s gs and stru f Part 24.02 s certified of	The sust ut.	e nose wheel lar tained substantia of the Civil Aviat 21 April 2005 at	nding al dam tion R a tota	gear strut nage to the egulations al of 108.2
Probable Cause											
The nose wheel shimmi over onto its roof.	ed and bi	roke off	; the	strut subseq	uently	contact	ted the run	way	y surface, and th	e airc	raft nosed
IARC Date					Rele Date		Reviewed	d by	/ EM office: AIID	Octo	ber 2009

|--|