



NOTIFICATION

This report contains short preliminary information about a serious incident in Switzerland without pretension to completeness and without conclusions. An investigation is in progress by the Swiss Accident Investigation Board.

Place, date and time: Zurich Airport (LSZH), 17 October 2014, 08:40 UTC

Aircraft:

Registration Mark: YU-APA
Type: Airbus A319-132
Operator: Air Serbia a.d. Belgrad
Owner: CIT Aerospace International

Pilot: **CMD** Serbian citizen, born 1968
F/O Serbian citizen, born 1967

Cabin crew: 4

Passengers: 119

Flight:

Flight rules: IFR
Type of operation: Commercial
Point of departure: Zurich (LSZH)
Point of landing: Belgrade (LYBE)

Damage:

Crew: None
Passengers: None
Thirds: None
Aircraft: Oil leak on right engine (engine No. 2)
Ground: None

Short description of the serious incident: Shortly after departure, the flight crew discontinued the climb due to oil leak from the right hand engine and landed minutes later on runway 28 with the right engine switched off.